



2015 Icebreaker Session



RVTEC Annual Meeting
November 3-5, 2015




THE RESEARCH VESSEL
F. G. WALTON SMITH
ROSENSTIEL SCHOOL OF MARINE AND ATMOSPHERIC SCIENCE



R/V Thomas G Thompson

Operational & Logistical Challenges:

- Four 8,000lb surface buoys
- Finding a winch in the last minute



R/V Clifford Barnes

Technical Challenges:

- Wifi cellular data use in Puget Sound
- CTD conducting cable: not just your termination can go bad!






W

UNIVERSITY of WASHINGTON



R/V ATLANTIC EXPLORER


2015 Update & Serial Communication troubleshooting





R/V Atlantis

Woods Hole Oceanographic
Institution



A Telepresence System for the R/V *Endeavor*






09/15/2005

University Of Hawaii

Markey Desh-5



Scripps 2015 overview

Sproul

- Biodiesel
- Active year

Revelle

- Lots of international logistics
- Install of GX system
- Decommissioning:
 - R/V Melville
 - R/V New Horizon

USCGC Healy

- Actually breaking ice
- Collaborative effort
- Made it to north pole

Breaking in the New Tech on the R/V Pelican




But it weighs a lot!
But it doesn't fit over the stern!
But it won't fit on the deck!



R/V Marcus G. Langseth

Dual Recording systems : Dual Navigation Systems

Primary: P-Cable and NavPoint
Secondary: Syntak and Spectra
Source: Digishot




Problems:

- Cannot Split: 1 Nav system for 2 recording systems
- Triggering of all systems must match or seismic data will fluctuate

How to trigger everything at once?

- Both Nav Systems using same GPS feed and NRP (to ensure identical positions)
- NavPoint System Triggers Source



R/V SIKULIAQ

Icebreaker Session

RVTEC 2015

Zabbix



R/V Sikuliaq

School of Fisheries
and Ocean Sciences

<https://www.sikuliaq.alaska.edu>





Significant Challenges:

13 of 16 ships delayed – CR Funding

- still realized an 83% utilization rate

GU – Loss of Automatic Gyro Data

- installed Lemmings on Serial output ports on Gyro to distro


RB – Installed IRIDIUM Pilot System to support Arctic Mission

- no loss of VSAT, even with 5-degree look angle



“Gremlins of the North”


- Multibeam software issues above 86N
- Poor multibeam/Knudsen in ice and during ice stations
- XBT issues in ice
- Satellite ice imagery issues
- Equipment vulnerability to cold





USAP Icebreaker's Icebreaker






- R/V Falkor's First Seismic Cruise
- Seamount named after the R/V Falkor
- Over a quarter million square kilometers mapped since 2014
- New CTD LARS, new 0.322 wire
- New NEBULA super computer
- SOI's 4500m ROV development well underway. On track for sea trials mid-2016.





The Encoder, the Winch, & the Wardrobe (Sensorless Vector Mode)



Systems Interface Inc.

COMPANY: MARKEY MACHINERY CO., INC. BALDOR 18H VECTOR DRIVE PARAMETERS DATE: 00/00/00 REV: 0
 PROJECT: DESF-4 RESEARCH WINCH DRIVE SYSTEM (SEA) S18-3.15 S18 JOB: S01K25
 ENGINEER: SED 10HP 230VAC

Date Printed: 30 Oct 15 08:02 W3+EQUIPMENTHydrowinch.etc\CC\HW_Motor - Mallorca - Sept 2015\501K25 Sensorless Vector-18HA.S0.XL5\18HVFD


BLOCK	PARAM	PARAMETER	UNITS	MIN/MAX	FACTORY	DRIVE	SENSORLESS	COMMENTS
TITLE	NUMBER	DESCRIPTION		VALUES	SETTING	SETTING	VECTOR MODE	
LEVEL 1 BLOCKS								
PRESET SPEEDS BLOCK 0	P1001	PRESET SPEED #1	RPM	0-MAX SPD	0			<u>Sensorless Vector Mode:</u>
	P1002	PRESET SPEED #2	RPM	0-MAX SPD	0			Set Parameters P2506 "Encoder Counts"
	P1003	PRESET SPEED #3	RPM	0-MAX SPD	0			form 1024 to 0. P2506 is located in the
	P1004	PRESET SPEED #4	RPM	0-MAX SPD	0			Level 2 Blocks under "Motor Data"
	P1005	PRESET SPEED #5	RPM	0-MAX SPD	0			
	P1006	PRESET SPEED #6	RPM	0-MAX SPD	0			The drive will reboot after the
	P1007	PRESET SPEED #7	RPM	0-MAX SPD	0			Encoder Counts parameter is changed.
	P1008	PRESET SPEED #8	RPM	0-MAX SPD	0			After rebooting, re-enter program mode
	P1009	PRESET SPEED #9	RPM	0-MAX SPD	0			and change the parameters in the blue
	P1010	PRESET SPEED #10	RPM	0-MAX SPD	0			sensorless vector mode column.
	P1011	PRESET SPEED #11	RPM	0-MAX SPD	0			
	P1012	PRESET SPEED #12	RPM	0-MAX SPD	0			<u>To change back to Vector Mode:</u>
	P1013	PRESET SPEED #13	RPM	0-MAX SPD	0			Set Parameters P2506 "Encoder Counts"
	P1014	PRESET SPEED #14	RPM	0-MAX SPD	0			back to 1024 from 0. Drive will reboot.
	P1015	PRESET SPEED #15	RPM	0-MAX SPD	0			
	ACCEL/DECEL RATES BLOCK 1	P1101	ACCEL TIME #1	SECONDS	0-3600	3.0	2.0	5.0
P1102		DECEL TIME #1	SECONDS	0-3600	3.0	2.0		as required, all parameters in the
P1103		S-CURVE #1	PERCENT	0-100	0	25%		"Drive Settings" column shown in red.
P1104		ACCEL TIME #2	SECONDS	0-3000	3.0			

- DESF-4 Winch | 10HP Motor | VF Drive
- Damaged sensor module = no control
- Pulse wheel also misaligned
- Sensorless Vector Mode
 - Allowed operation, albeit reduced
 - Less fine-tune control at near-0 RPM
 - Slower top-speed (35m/m)


Alex Sneddon

Stony Brook
University





January 30, 2014



Tom Wilson added 3 new photos.

January 30, 2014 · Edited

PLEASE LIKE AND SHARE.

HELP TRACK THE GREAT SOUTH BAY DATA BUOY.

The Great South Bay Data Buoy is a project of Stony Brook University's School of Marine and Atmospheric Sciences. Since October 2010, the buoy has provided weather and water quality information to government, researchers, and the general public.

After surviving Irene and Sandy and being dragged around by the ice for three winters with no major problems, the buoy suffered a loss of telemetry on January 25th. Without telemetry we have no GPS position, so we are asking for help to keep track of the buoy until the ice breaks and we can retrieve it for repairs.


The buoy's normal position is 40d 41.96m N, 73d 05.21m W, south of Green Creek in West Sayville. Last GPS position was 40d 41.96m N 73d 1.67m W, south of Blue Point, at 5:00am EST on 1/25/2014.

If you see the buoy, please post or message me with date, time, and position. If you get close enough to take pictures (iceboaters?) that would be great too. If the buoy has broken free of the mooring and is adrift please take all reasonable steps to secure or retrieve it, otherwise a report of position is sufficient.

Thanks for your help!

Tom Wilson

Stony Brook University



Original Buoy location

Buoy Location








DATA BI













Thank you!