



Research Vessel Operators Committee El Faro accident

University of Rhode Island April 17-19 2018










The Accident Voyage - September 30



```
BC Massage --- MET Wavarea Warning or MET Forecast ---
Sessage Sessionce No. : 12704
                     : Vizada (NOR)
riority
                     # 2191 Characters
scalve Date & Time : 16-10-16 20146 (UTC)
TIR LES 18-007-2018 20144415 089791
VINT25 XWHC 162043
CHATS ADM 2043
EURITCANE NICOLE FORECAST/ADVISORY NUMBER 51
MS NATIONAL HURRICANE CENTER MIAMI FL
2100 UTC BUN OCT 16 2016
HERE ARE NO COARTAL WATCHED OR WARNINGS IN EFFECT.
EMPRICANE CONTER LOCATED NEAR SY. 7N NS.64 AT 16/21002
POSITION ACCURATE MITHIN 30 NM
 RESENT HOVEHENT TOWARD THE HORTHEAST ON 45 DEDREES AT 8 KT
ESTIMATED MINIMUM CENTRAL PRESSURE 940 HD
TYE DIAMETER TO MM HAN SUSTAINED WINDS TO ME HT.
4 KT..... SONE BOSE BOSM TOWN.
  KT......130NE 1508E 1809M 130NM
14 KT......300NE 330SE 330SW 380NW.
2 FT SEAS, 490NE AAORE 940SM 720NM
 INDS AND BEAG WARY GREATLY IN EACH GUADRANT, RADII IN HAUTICAL
TLES ARE THE LANDEST MADLE EXPECTED ANYMHERE IN THAY GUADRANT.
REPEAT...CENTER LOCATED NEAR 39.TN 45.AN AT 16/21002
 T 16/18002 DENTER WAS LOCATED HEAT 39.4H 40.9W
"CHECAST VALID 17/0800Z 40.5N 44.5N
MRE WIND AS ET...BUETS BO KT.
54 KT... GOME BOSE BOSW 70NM.
0 KT...130ME 150SE 180GW 150MW.
A KT...400ME JOSE 3506W 420MW.
DESCRIPT WAS IN 17/18007 47.48 AS WE
MAX WIND 65 KT. . . GUSTS GO KT.
  KT...130ME 150SE 140SH 110NH
  KT...420NE 400BE 380BW 480NW
CRECAST WALID 18/04002 46.3N 39.4H...POST-TROP/EXTRATROP
FR WINE 65 KT... BUBTS BO KT.
A KT ... BONE FOSE FORM SONN
O KT...130NE 1408E 1208W 90NW.
4 KT...450NE 450SE 400GW 550NW.
CRECAST VALID 18/18002 51.3W 37.3W...POST-TROP/EXTRATROP
WAX WIND AS KT...GUSTS BO KT.
4 KT ... 480NE SLOSE 430SW 450NW,
CRECAST VALID 19/18002 59.6N 32.7W...POST-TROP/EXTRATROP
MAN WIND 55 KT...GUSTS AS KT.
90 KT...120NE 240BE OSW ONW.
54 KT...360NE 400GE 420GN 600NW.
```


BVS

Sat-C


The Accident Voyage – September 30



The Accident Voyage – September 30



Possible Routes between Jax and San Juan




The Accident Voyage – September 30





Dynamic Analysis




Downflooding from Watertight Scuttle (Deck Hatch)







Watertight Deck




- Boarding seas (green water) was known to enter onto 2nd deck in past
- Partially enclosed 2nd deck was watertight

Cargo Hold 3 Tanktop (4th Deck)






Extreme list to port




18° list to port – looking forward




Extreme list to port






Cargo Hold Ventilation Downflooding



El Faro Cargo Hold 3
















Safety Issues

- Loss of propulsion
- Flooding in cargo holds
- Downflooding through ventilation closures
- Need for damage control plan
- Lack of suitable survival craft
- Late decision to muster the crew

Safety Issues

- Inadequate company oversight
- Company's safety management system
- Ineffective bridge resource management
- Use of noncurrent weather information
- Captain's actions

Other Issues

- Alternate Compliance Program
- Voyage data recorders
- Expanded use of automatic identification system

Safety Recommendations

- USCG and ABS on Alternate Compliance program
- IACS, ABS, USCG on stability information
- NOAA on weather information to mariners
- NOAA on exploring the use of AIS for observations
- TOTE on Safety Management
- USCG on survival craft, use of PLBs
- FCC on old EPIRBS and AIS frequencies

Contact

- Brian Curtis, Director
 - 202-314-6456
 - Brian.Curtis@NTSB.gov
- Morgan Turrell, Deputy Director
 - 202-314-6106
 - Morgan.Turrell@NTSB.gov
- Liam LaRue, Chief of Investigations
 - 202-314-6492
 - Liam.LaRue@NTSB.gov

