

Woods Hole Oceanographic Institution



R/V Atlantis Bow Thruster Issue





- Replaced 3 of 4 bolts that backed out from anti-torque plates after maintenance in Jacksonville.
- Specs required bolts to be tack welded (they were not).
- Repairs required drydocking in Mar 2003.
- Only available dry dock was Grand Bahama Ship in Freeport, Grand Bahamas.
- 10 day delay (7 going in & 3 coming out) encountered due to availability of dry dock.
- •Claim has been filed against Atlantic Dry Dock Corp to recover costs & loss of 6 science days.









R/V Atlantis Plans for Woods Hole Port Visit

August – October 2003

• A-frame maintenance

Replace main cylinder block fasteners Replace wasted main cylinder 2" piping Replace main supply piping up A-frame leg Replace 4-bolt flange on both sides of main hoist Replace anti-swing relief valves Refurbish tail winch Perform general corrosion maintenance

- Install Counterbalance sheave on port hydro boom
- Hiab crane maintenance
- Install fire door magnets around galley
- Switchboard maintenance
- Main Breaker maintenance
- Hydro Winch maintenance as required after assessment in Bermuda
- Clean Generators (if funds available)
- Hurricane Mooring Plan



