


Healy Science Modifications, Infrastructure, and Equipment



Dale Chayes <dale@ldeo.columbia.edu>
Instrument Lab
Lamont-Doherty Earth Observatory
of Columbia University

Seawater Systems

- Develop clear definition of the needs? \$
 - Incubators, TSGs, sinks, samples
- Include adequate water “aft”
 - Sinks, samples, wash down, sample wash,
?
- Add TSG “forward” \$
- Improved plumbing going aft \$\$



Drain as appropriate

Detailing Flow Meter

Sink 32" High
20" x 24"

24" x 24" x 24"





24" x 24" x 24"

Watch Standers Work Station

- Prototype was used during 2005
- Some enhancements likely in '06
 - Improved display software
 - Upgraded displays
 - Improved mounting



U.S.
COAST
GUARD




Walk-in chambers (2 “controlled”, 2 “cold”)

- They perform as specified in the SOR
- That does not seem to be good enough
- We need better definition(s) \$
- Then we can design \$
- And propose changes [\$ | \$\$ | \$\$\$]
- Remember that they are used for other things too.

Lab Space Improvements


- Computer Lab (\$\$)
 - Might be possible in 07 off season
- Future Lab (\$)
- Met Lab (\$)
- Aft Con
 - Lockers, access... \$
 - Improved visibility \$\$
- 02 Copier Room \$
- Aft Staging \$

Aft Con






Computer Lab






Future Lab w/ darkroom








Consider moving the door to improve flow





USCG Healy
Aft Staging
Main Deck Level
Unistrut on 2' Centers





1-27-08
PM 2:27-1

INGONYA
SCIENCE
S.K.

Multibeam

- There are significant support issues now (O & M 'til 2010 \$\$)
- Substantial performance & operational improvements are possible
- Review the science needs \$
- Under hull ship check in DD07 \$
- Earliest realistic change is 2010 \$\$-\$\$\$

Subbottom Profiler

- Healy had two very different systems (Bathy 2000 and Knudsen 320BR)
 - Significant cost for training and maintenance
- Autopilot (\$\$) was going “upgrade” the Bathy
 - Adjusted the plan at the last minute (PSEA & STAR?)
- Knudsen is more stable and supportable
- Spent less to have two 320BRs & retire the Bathy 2000

Terascan

- Upgrade from 1m to 1.5 m antenna (\$\$)
 - Didn't quite make it last year
 - Happening now
 - Test and accept during HLY06TD
 - Add alternate choices for heading input
- Borrow Terascan license from Star for HLY06 to allow image processing independent of the WDS

Broad band hydrophone

- Healy was delivered with a DT-513c that has been re-discovered and (mildly) tested in the ADCP performance which hunt.
- Add suitable acquisition and display capability (\$)



Start 0 Hz Stop 200 kHz
 Res BW 1 kHz VBW 1 kHz Sweep 257.7 ms (401 pts)

Pk	X Axis	Amplitude	Pk	X Axis
1	12.0 kHz	0.267 dBm	6	36.0 kHz
2	24.5 kHz	-8.609 dBm	7	149.0 kHz
3	48.0 kHz	-11.82 dBm	8	133.0 kHz
4	40.0 kHz	-26.84 dBm	9	96.5 kHz
5	54.5 kHz	-30.19 dBm	10	144.5 kHz

C:\SCREN019.GIF file saved

Trace/View


Trace 1 2 3

Clear Write

Max Hold

Min Hold

Observed spectra (HLY06TC)



Start 0 Hz Stop 200 kHz
 Res BW 1 kHz VBW 1 kHz Sweep 257.7 ms (401 pts)

Pk	X Axis	Amplitude	Pk	X Axis	Amplitude
1	63.0 kHz	-77.66 dBm	6		
2	73.0 kHz	-79.12 dBm	7		
3			8		
4			9		
5			10		

C:\SCREN015.GIF file saved

Trace/View

Trace 1 2 3

Clear Write

Max Hold

Min Hold

View

Blank

More 1 of 2

Improved MapServer

- Steve Roberts is working on the code
- Add a higher performance, dedicated processor for the MapServer and it's supporting processing (\$)
- Add daylight readable displays in Aloft Conn and Aft Conn (\$)

Equipment Purchases (2006)

- Spares & Repairs:
 - SB2112 circuit boards
 - LDEO logging and displays
 - Sheave spares
 - ADCP spares
 - Continued troubleshooting of ADCPs

Concerns and issues

- Shipboard power

<http://ilab.ideo.columbia.edu/Members/dale/how-to/shipboard-power-systems-are-different/>

- Improved Internet access for science on Healy

- Access to the pool of icebreaker science gear:

Historically the collection of science gear has been treated as a pool. Star's new status appears to have changed that.

Fiberoptic 0.68" tow cable

- Did a temporary installation for 2005 (\$\$)
- Will do a temporary installation for 2006 (\$\$)
- Gakkle in 2007 requires one (\$\$)
- Temporary installs are:
 - Expensive (logistics, ship time, equipment, etc.)
 - A compromise at best
 - Consume substantial deck space
- Options:
 - FO cable on existing winch (\$)
 - New Winch (\$\$-\$\$\$)

Inmarsat Upgrade

- CG is exploring upping the theoretical bit rate from 64kbps to 128 kbps
 - Actual throughput is less and unknown to me
- We have proposed to “share” this bandwidth in a secure and rate-controllable manner.
- Neither will happen for ‘06

Plans/needs for 2007

- Drydock upgrades
- Need to know the science
- Need input from AICC

Long Term Plans

Serious mid-life planning starts “now” for 2015

- High latitude communications
 - Improved Iridium
 - Vsat
 - TDRS (continue to explore)
- High latitude navigation
 - Globally Corrected Differential GPS
 - ?