



OUTLINE

- (1) ADCP+UHDAS installations
- (2) Attitude (Heading) comparison
- (3) RDI/RTI comment
- (4) Show and Tell – cool device

(1) ADCP+UHDAS Report

RVTEC Nov 2013 – UHDAS/ADCP

Time,
ADCP
Position
Attitude



primitive data

ocean velocities

UHDAS Goals

- Acquisition: reliable, robust, duplicate feeds
- Monitoring and **remote troubleshooting**
- Processing
 - Balance real-time output and post-cruise recovery
 - Minimal effort to “touch up” (if all goes well)
 - Portable code and **documentation**
- Happy Scientists
- Happy Techs

UHDAS Installations

- **14 UNOLS ships:** Atlantic Explorer, Atlantis, Endeavor, Kilo Moana, Knorr, Langseth, Melville, New Horizon, Oceanus, Point Sur, R.Revelle, R.G.Sproul, T.G.Thompson, F.G.Walton Smith
- **3 polar ships:** Healy, L.M.Gould, N.B.Palmer
- **2 NOAA ships:** Hi`ialakai, Ron Brown
- **1 “other” ship:** Ka`imikai O Kanaloa

- 1 “cooperative” installation – Tioga

Improvements since last RVTEC

- Code base
 - Removed use of Matlab
- UHDAS Installation
 - Upgrade to 12.04 Xubuntu (ongoing...)
 - Require: streamline multiple install methods
 - Goal: 'UHDAS' install from ISO (getting closer)
- Science Data User
 - Improve graphical editing tool
 - update documentation+virtual computer

Installations status

- All are running Python (no Matlab):
- Ships updated to Xubuntu 12.04:
 - Atlantic Explorer, Atlantis, Hi`ialakai, Healy, Kilo Moana, Knorr, KOK, L.M.Gould, N.B.Palmer, Oceanus, Ron Brown, T.Thompson, Walton Smith, Oceanus
- Ships needing this update
 - Endeavor, Langseth, Pt Sur, Melville, Revelle, Sproul, New Horizon
- New Installations:
 - Sikuliaq, (Pelican, (Falkor))

Problems: Attitude (ongoing)

- Ashtech
 - some resets required; some failed completely
 - new antennas; new termination made MUCH better
- Phins are not perfect
 - (occasionally) uncalibrated; or fails
- Seapath (occasionally) needs to be reset
- Coda-f185: requires a reset when leaving port
- POSMV various status:
 - only 50% of them are solid, rest glitchy (or broken)


ADCP Problems (since 2/2013)

- Langseth: OS75 failed (unknown cause)
- Walton Smith
 - BB600 lost one beam
 - OS75 failed (WHOI loaned OS75 in time for cruise)
- Melville: OS150 repaired, but still loses data on station
- Falkor
 - WH300 failed
 - OS75 failed
- Kilo Moana:
 - WH300 (bad trace; failed in warm water)

Healy:

Most Dramatic
Example of
EMF Noise

Transducer Cables: Proximity to Ship Cable Bundle Affects Range



Expectations for 2014

- Update more ships to Xubuntu 12.04
- 1+ new installation
 - Sikuliaq
- Work with R2R+NOAA regarding ADCP data
- Revisit Documentation
- Continue to streamline installation process

Continuing Request: Keep us in the loop regarding


- New ADCP (requires configuration, calibration)
 - Includes special needs by Science
- Changes in serial feeds
- New attitude devices (we like to evaluate them)
- changes in networking
 - route to ship
 - infrastructure on ship

Protocol

- Always run “End Cruise” before archiving
- If rsync (regular backup)
 - **ALWAYS** use complete cruise name

(2) Attitude (Heading) Comparison

Most Open Ocean currents are quite small; under 0.2m/s




ADCP challenge:

(1) Signal:

open ocean currents are quite small,
often under 0.1-0.2m/s


(2) Error:

1° heading error at 10kts causes
0.1m/s error in ADCP ocean current
- error is in crosstrack direction



same size as
ocean currents

Are these actual currents? or fiction (from heading error)



os75bb: last time 2010/11/11 19:22:16


Heading devices used by UHDAS installations (Nov 2013)

Ship	<u>Ashtech</u>	<u>Mahrs</u>	<u>Phins</u>	Coda	POSMV	<u>Seapath</u>	gyro note	gyro
Atlantic Explorer	ADU5							<u>Sperry</u> MK37
Atlantis			Phins3 Phins3					<u>Sperry</u> MK37E
Endeavor	ADU2 ADU5							<u>Sperry</u> MK37
<u>Hi'ialakai</u>					320v4			Meridian Standard
Healy	ADU5				320v2 320v2		FOG	<u>Sperry</u> MK27 <u>Sperry</u> MK39
KOK		TSS						?
Kilo Moana					320v4			<u>Sperry</u> Decca <u>Bridgemaster</u> E250
<u>Knorr</u>			Phins3		320v3			<u>Sperry</u> MK27
L.M.Gould						330 (200)*		Meridian <u>Bridgemate</u>
<u>Langseth</u>					320v?			<u>Sperry</u> GC80
Melville	ADU2			F185				Meridian Surveyor
New Horizon	ADU2							<u>Sperry</u> MK37
N.B.Palmer						200 200 (300*)		<u>Yokogawa</u> KM008-E
Oceanus	ADU5							<u>Sperry</u> MK37
Point Sur	ADU5							<u>Sperry</u> Gyrosphere TS-X
Ron Brown		TSS			320v4			Meridian Standard
<u>Revelle</u>	ADU2		Phins3				inertial	<u>Hydrins</u>
<u>Sproul</u>	ADU2						2GPS+tilt	<u>Furuno</u> sc-30
Thompson					320v4			<u>Sperry</u> MK37
Walton Smith					320v2			<u>Meridan</u> (xx)


←
→

\$20K
\$80-\$120K


Comparison: various heading devices vs/ accurate heading device plotted: 1-2 standard deviations (as in ADCP processing)



1-2 stddev(ADCP heading correction) i.e. 5-min edited dh




Histogram of ocean speeds



Most open ocean currents on these cruises were centered at 0.1m/s

heading ERRORS



1deg heading error at 10kts makes a 0.1m/s error in ocean currents (crosstrack)

Final request

... as always:

Send your needy scientists to Jules

(3) RDI/RTI Comment

RDI (Teledyne **R**D. Instruments)

RTI (Rowe Technologies Inc)



Cool Tool

www.isostick.com



isostick

Eliminate piles of burned CDs & slow load times. Whether you're a seasoned IT Pro or just tech support for friends & family, isostick can make your life easier (though you'll need a new source of coasters).

[➔ Buy Now](#)

[➔ Buy Now \(US\)](#)