

### **NSF Wire Pool**

**Eric Trotto** 



### Introduction

- Over the past year I have transitioned to the Manager of the Wire Pool.
- I have worked at WHOI (Mooring Lab, Physical Oceanography) since 2014.
- Rick Trask officially stepped down in January of 2025.

# Maintain An Inventory of Wire Rope, Cable, and Synthetic

One Wire Pool, two storage facilities

- East Coast Woods Hole Oceanographic Institution (WHOI)
- West Coast Scripps Institution of Oceanography (SIO)

#### Inventory of Commonly Used tension members

- Wire Ropes: <sup>1</sup>/<sub>4</sub>", <sup>1</sup>/<sub>2</sub>", 9/16"
- Cables: .322 EM, .680" Coax, .681" power optic Other tension members
- Synthetics: 9/16" Plamsma HiCo

# **Requesting New Wire**

- Wire Pool fields all requests for new and used tension members
- Determine availability of requested item (inventory)
- Wire Pool prepares package for NSF consideration
- If approved, arrange for shipping to nearest domestic port
  Long Lead Times

.681: 8 Month lead time 3x19: 4 Month lead time

# **Database and Break Testing**

- Wire Pool launched a new database January 2025
- Marine Superintendents have access to tension members assigned to vessel
  - Update wire status
  - Manage SWL information
  - Report Events
    - Lubrication, cutbacks, splits, document upload
  - Submit break test request
    - Testing mandated by Appendix A of RVSS and funded by NSF (no cost to vessel)

# Fibron RM0049


#### First Time in field

- Behaved well electrically and optically
- Need to condition before use
  - This helps avoid twisting and damage to cable
- Added ship time to condition new cable

## Problems

### •.681

- A309063: (2) cables in fleet both failed
  - K-tube causing fault with conductor
  - Rochester acknowledged problem and warrantied one cable
  - Replaced with A310114 good track record (no K-tube)
- ¼"3x19
  - Manufacturer metallic problem causing low breaks



# **Questions?**