## Feedback Response - Jason

- Not clear to PI that supplying digital bathy was preferred
  - Multibeam data important for DVL overlays
- LBL navigation not used, Doppler performed poorly on steep slopes
  - 300 kHz Doppler still does not work properly on steep terrain
- First use of new control vans seemed to work well, although screen layout changed from watch to watch. Could it be standardized?
  - First cruise sort out with experience
- Dive durations were "over-zealously inflexible"
  - Need a steady cycle for ops team; first time we tried
    8-hour turnaround time







