SWAB REPORT # 553

SWAB DATE: 10 August 2010

R/V Melville

Dr. James D. Happell Associate Research Professor

Distribution: SWAB Committee Scripps Committee Gary Lain

REPORT FOR SWAB # 553

LOCATION: San Diego, CA

TECHNICIAN: Cecilia Roig

DATE: 10 August 2010

STATUS: See Comments

VESSEL/LAB: R/V Melville

SAMPLE	SAMPLE IDENTIFICATION	NET ACTIVITY	NET ACTIVITY EXTRACTED	
#		³ H dpm/m ²	$^{14}\text{C dpm/m}^2$	
1	1st Machine blank	0	0	
2	Initial bucket blank C.O. #1	13	18	
			- 0	
	Winch Room (See Figure 1)			
3	Inside Revco	0	11	
4	Inside Kenmore	34	0	
5	Inside Frigidaire	10	36	
6	Deck in front of Revco	29	10	
7	Deck between Kenmore & Frigidaire	28	3	
	Main Lat. (Qua Finance)			
0	Main Lab (See Figure 2)	34	2	
8	Bench top aft of sink		3	
9	Inside sink and sink area	23	19	
10	Deck between bench tops	21	25	
11	Inside Kenmore freezer	13	18	
12	Bench top fwd. of sink	40	13	
13	Bench top across sink	257	18	
14	Inside Sanyo freezer	0	7	
15	Deck in front of freezer	0	9	
16	Bench top port of Sanyo	63	15	
17	Deck center of lab	2	47	
18	Deck at entrance to stairs	3	23	
19	Inside Kelvinator	0	16	
20	Deck in front of stairs	1	11	
21	Bench top across Kelvinator	13	26	
22	Stbd. bench top	47	25	
23	Intermediate bucket blank	0	28	
	Analytical Lab (See Figure 2)			
24	Inside hood	0	27	
25	Deck inside door to Main Lab	16	22	
26	Sink area	0	26	
27	Fwd. port bench top	2	9	
28	Deck in front of sink	16	56 *	

SAMPLE	SAMPLE IDENTIFICATION	NET ACTIVIT	NET ACTIVITY EXTRACTED	
#		3 H dpm/m 2	$^{14}\text{C dpm/m}^2$	
29	Stbd. bench top	0	14	
30	Deck inside stbd. door	32	24	
31	Bench top fwd. of hood	0	52 *	
32	Final bucket blank C.O. #1	0	7	
33	Initial bucket blank C.O. #2	24	17	
	01 Deck (See Figure 2)			
34	Deck at entrance to library	4	12	
35	Outside deck	17	13	
36	Deck at top of stairs	21	16	
37	Deck at end of game table	3	7	
	Dark Room (See Figure 2)			
38	Sink area	1	24	
39	Deck inside aft door to hangar	0	29	
40	Deck in front of sink	0	13	
41	Deck inside fwd. port door	4	11	
	Misc. Areas (See Figure 2)			
42	Deck outside entrance to hospital	3	17	
43	Deck outside aft entrance to galley	0	9	
44	Deck outside fwd. entrance to galley	12	26	
	Aft Hangar (See Figure 2)			
45	Sink area	27	0	
46	Deck at entrance to Main Lab	29	27	
47	Final bucket blank C. O. #2	7	7	

Comments

Minor ¹⁴C contamination found in two samples taken in the Analytical Lab. These areas will need to be cleaned before any natural tracer work.