SWAB REPORT # 588

SWAB DATE: 22 July 2011

R/V Melville

James D. Happell

Distribution: SWAB Committee Gary Lain

REPORT FOR SWAB # 588

LOCATION: Point Loma, San Diego, CA DATE: 22 July 2011

VESSEL: R/V Melville TECHNICIAN: Charlene Grall

Sample # Sample Identification	³ H dpm/m ²			¹⁴ C dpm/m ²		
	activity	(error	activity		error
1 1st Vial Bkgnd	0	±	0	0	±	0
2 Bucket Blank CO #1	41	±	69	0	±	0
Main Lab (See Fig 1)						
3 Wooden bench top across & slightly aft of port sink	47	\pm	52	0	\pm	0
4 Wooden bench top aft of sink	23	\pm	42	3	\pm	25
5 Deck in front of aft Kenmore freezer	42	\pm	46	1	\pm	14
6 Deck outside of lab entrance	36	\pm	50	0	\pm	0
7 Deck at entrance to aft stairs	80	\pm	53	0	\pm	0
8 Deck in front of Sanyo -80C freezer	92	\pm	55	0	\pm	0
9 Deck between starboard entrance and Kelvinator	71	\pm	45	3	\pm	16
10 Deck in front of passage to forward areas	51	\pm	47	0	\pm	0
11 Deck in front of computer benchtops	59	\pm	51	0	\pm	0
12 Deck across from starboard entrance	67	±	49	0	±	0
Analytical Lab (see Fig 1)						
13 Deck inside aft entrance	53	\pm	52	0	\pm	0
14 Inside fume hood	108	±	55	0	\pm	0
15 Sink area	57	±	42	5	\pm	22
16 Forward benchtop	79	±	51	0	\pm	0
17 Deck inside starboard entrance	41	±	42	0	\pm	0
18 Deck in front of sink	91	±	48	0	\pm	0
19 Benchtop across from sink	70	±	48	2	±	11
Aft Deck (see Fig. 1)						
20 Workbench where rad bottles stored	31	±	111	0	\pm	0
21 Deck where samples stored	82	\pm	61	0	\pm	0
22 Deck at A-frame where CTD came onboard	146	\pm	64	0	\pm	0
23 Deck aft of A-frame where entrance to rad van was	208	±	64	0	\pm	0
24 Deck forward of where incubators were set up	236	±	56	0	±	0
02 Deck (No figure)						
25 Deck where door to rad waste van opened	98	±	57	0	±	0

Sample # Sample Identification	³ H dpn	³ H dpm/m ²			¹⁴ C dpm/m ²		
	activity		error	activity		error	
Dark room (See Fig. 1)							
26 Sink area	92	±	43	0	\pm	0	
27 Benchtop across from sink	0	\pm	0	0	\pm	0	
28 Deck inside aft entrance	20	±	103	0	\pm	0	
29 Deck in passage outside of forward entrance	10	±	0	0	±	0	
Miscellaneous areas (see Fig. 1)							
30 Deck at forward entrance to mess	0	±	0	0	\pm	0	
31 Deck at aft entrance to mess	0	\pm	0	0	\pm	0	
32 Upper lab deck in front of design jet printer	0	\pm	0	0	\pm	0	
33 Passageway deck outside library	9	±	0	0	\pm	0	
34 Final bucket blank CO #1	0	±	0	0	±	0	
Radioisotope Van #12 (see Fig. 2)							
35 Initial bucket blank CO #2	0	±	0	0	\pm	0	
36 Benchtop opposite sink	17	±	0	0	\pm	0	
37 Fume hood and adjacent benchtop	207	±	88	0	\pm	0	
38 Inside refrigerator	437	\pm	97	0	\pm	0	
39 Inside freezer	*8017	\pm	210	**12062	\pm	189	
40 Benchtop above refrigerator	8	±	41	8	\pm	35	
41 Benchtop above freezer	18	±	92	0	\pm	0	
42 Sink area	31	±	115	0	\pm	0	
43 Deck in front of entrance by fume hood	117	\pm	59	0	\pm	0	
44 Deck in front of entrance by sink	134	\pm	61	0	\pm	0	
45 Intermediate bucket blank CO #2	9	±	0	0	±	0	
Waste Rad Van (No Figure)							
46 Deck at back of van	118	±	58	*66	±	37	
47 Deck on right side of van	278	±	85	*52	±	32	
48 Deck on left side of van	269	±	93	*62	±	34	
49 Center deck in van	259	±	82	*91	±	37	
50 Deck in front of double doors	*1682	±	141	*213	±	34	
51 Final bucket blank CO #2	0	±	0	0	±	0	

Comments

Please note that the error reported for each isotope is the two-standard deviation counting error. All areas tested on the ship were free of contamination. Radioisotope Van freezer tested positive for minor ³H and ¹⁴C contamination. We recommed that the freezer be cleaned.

The Waste Rad Van had minor ³H and ¹⁴ C contamination. No action required.

R/V MELVILLE



