

Safety Committee Task Statement

- Define the best operating procedures for over the side cables, to include:
 - Max working load as a percentage of yield
 - Deck operation procedures to limit potential exposure
 - Incoming and routine yield testing to determine actual yield