Alvin de-brief summaries - 6/08

Three cruises for 32 dives All at EPR with ports in San Diego and Manzanillo

Millineaux	Nov 2007	EPR
Van Damm	Dec 2007	EPR
Sievert	Jan 2008	EPR

Pre-Cruise Planning:

- All went very smoothly mostly very experienced users
- Not all of the information for interfacing userprovided sensors with Alvin systems that was sent through to the ship arrived

Mobilization/Demobilization:

- Most gear loaded/unloaded in San Diego so no issues
- Mixed reports on local agent Good service but costs sometimes inflated over original agreedupon price (not an NDSF issue but it impacts us)

Operations - Vehicle:

No failings that impacted science or otherwise Port manipulator failed once but all dive objectives achieved and arm repaired by next day

Batteries performed excellent and science parties enjoyed good duration bottom times

Operations - NDSF Equipment:

- LBL navigation already in place in most areas and worked well
- DVL sometimes lost bottom lock potentially due to rough topography at EPR
 Elevator deployments worked well
 Cameras worked beyond expectations

Alvin de-brief issues - 6/08

Operations - User Equipment:

Sensor packages were successfully interfaced to Alvin

Data hand-over:

All PIs satisfied with data hand-overStill some problems with science party bringing the wrong type of DVDsThere was a problem with the Alvin duping station on one cruise