





Old Receive array



EM122 receive casing



EM122 receive



New hole for 1° transmit



Transmit casing for EM122



Big Transmit (1°)



Surprise dent





Shafts were pulled



Electrolysis on Port Shaft



BB150 exchanged with UA phased

