




UNOLS Fleet Safety Statistics Report


2017

Quarter: 1st

No. of Ships Reporting: 14/17



Incidents (At Sea and In Port)	
Violence and other injuries by persons or animal	0
Transportation incidents	0
Fires/Explosions	0
Falls/Slips/Trips	4
Exposure to Harmful Substances or Environments	0
Contact with object/equipment	1
Overexertion/Bodily Reaction	3
Illness (including heart conditions, disease, etc.)	2
Other	0
Total Number of Incidents	10
Total Crew Days Reported (At Sea and in Port)	
Total Crew Days Reported (At Sea and in Port)	16,468
Number of Accidents Resulting in Lost Time for Crew Members	3
Total Crew Days Lost	7



UNOLS Fleet Safety Statistics Report

2017

Quarter: 1st

No. of Ships Reporting: 14/17

Incident Details	Warnings/Lessons Learned
<p>1) 3rd Engineer C/O abdominal pain after moving a heavy piece of Equipment. No lost work days/ Follow up up ashore/ Fit for duty- Strain- no hernia</p> <p>2) SSSG tech. fell on ladder well. Laceration to head and back pain. P&I case opened. Follow up ashore. Limited fit for duty- no heaving lifting.</p> <p>3) SSSG tech c/o of amdominal pain. Had history of hernia a few years ago. Treated and released in Costa Rica. Returned to ship with fit for duty.</p>	<p>Use caution when lifting or walking down stairs at sea.</p>
<p>Finger cut on sharp edge of cabinet shelf.</p>	<p>N/A</p>
<p>Scientist was exercising on the fixed chin up bar aboard and the weld on one side of the chin up bar broke. Scientist fell on to the deck and broke their collar bone.</p>	<p>Not something we do regularly but check ship's exercise equipment.</p>
<p>Crew fell while reaching for valve in overhead</p>	<p>N/A</p>
<p>Not clear when the incident occurred. The incident involved strain to the abdomen resulting in pain. Speculation is that this occurred while taking down and storing scaffolding. Placed on not fit for duty for one day and signed off the ship the next with completion of the assignment.</p>	<p>N/A</p>



UNOLS Fleet Safety Statistics Report

2017

Quarter: 1st

No. of Ships Reporting: 14/17

<p>1) AB strained back- seen at local clinic - fit for duty</p> <p>2) 1st engineer dad tooth ache- abscess- tooth pulled- returned to work</p>	<p>N/A</p>
<p>Trip and fall while walking off shipyard-supplied gangway on to pier.</p>	<p>Be aware of the accumulation of gear and tools around the areas where people are accessing a gangway.</p>